

60 YEAR OLD...

Urostomy patient experiencing severe leakage



Patient History

- Urostomy with retracted stoma
- Used convex seal with convex pouching system
- Experienced leakage up to 5 times per day
- Frequent leakage lead to flare-ups in sore skin



Introduced Ostoform Seal with FLOWASSIST

- Used with convex pouching system



Feedback

- "This product has been a raging success"
- Now changing his baseplate once every 4 days
- No leaks since using Ostoform, which has given his skin time to recover
- Skin is now healthy

Conclusion

The Ostoform Seal has changed this patient's life. He has gone from not knowing what each day will bring (1 pouch change or 5) to now reliably being able to change his pouch once every 4 days. Before Ostoform, he explained he sometimes did not want to leave the house, now he is going out dancing.

Ileostomy patient with complex fistula

Before Ostoform

- New end ileostomy after jejunostomy reversal
- Developed complex fistula post-op, which outputs more than 1 litre daily
- Uses a high output system with flow collector and daily TPN
- Position of the fistula points downwards and has a tracking at 1 o'clock



After 48 hours of using Ostoform

- 2 large Ostoform Seals are used to manage this fistula due to the positioning
- Changing appliance 2-3 times per day
- Patient was able to go home for the first time in months



After 4 days of using Ostoform

- Skin is no longer painful to touch, appliances are now comfortable and manageable



After 11 days of using Ostoform

- Skin condition significantly improved *

*Subsequent to this case study, the patient had surgery to refashion her ileostomy and surgical intervention on the fistula. The patient is now using the Ostoform Seal with FLOWASSIST on her ileostomy with positive results.



Note: The Ostoform Seal with FLOWASSIST was used off-label on the fistula under clinical supervision.



The New Standard in Skin Protection



www.ostoform.com

OFLS19#0

www.ostoform.com

All case studies were conducted under clinical supervision and provided by Ostoform's UK distribution partner, Rhodes Pharma Ltd.

40 YEAR OLD...

Ileostomy patient with extreme leakage from pancaking



Patient History

- Post-op ileostomy
- Retracted stoma
- Experienced extreme pancaking, which lead to frequent leakage (up to 10 times per day)
- Peristomal skin was irritated and sore to touch
- On average, was changing their pouching system 8 times per day



*Photo to right shows skin condition on day 1 of case study



Introduced Ostoform Seal with FLOWASSIST

- Used with 1-piece flat drainable pouching system



Feedback

- Now rarely experiences pancaking
- Leakage is now under control
- Skin breakdown is beginning to heal



*Photo to right shows skin condition on day 28 of case study

Quote from the Patient

"This product really has saved my life."

40 YEAR OLD...

Ileostomy patient experiencing leakage



Patient History

- Post-op with new end ileostomy with prior loop stoma
- Stoma OS points to the right
- Found convexity to be too uncomfortable
- Experienced leakage 2-3 times per day
- Experienced skin breakdown with sore and inflamed skin
- Leakage had impact on quality of life and daily activities



Introduced Ostoform Seal with FLOWASSIST

- Used with 1-piece flat drainable pouching system



Feedback

- Before Ostoform, surgical intervention was being explored for stoma revision - it is now thought this will not be needed
- Patient has now been using Ostoform for 6 months with no leakage
- Patient has an improved quality of life and describes the Ostoform Seal as "life-changing"

Quote from the Patient

"After trying several products to help with the positioning of my stoma, this Seal has succeeded. The Seal fits snug around the stoma and is comfortable. The spout is soft, flexible and discreet under clothing. I feel safe and secure with this product, and I am not as anxious as I was."

85 YEAR OLD...

Ileostomy patient requiring extended pouch wear time



Patient History

- Ileostomy
- Oval stoma that tilts downwards, but OS is central
- Patient has a parastomal hernia
- Has a history of leakage
- Tried a traditional hydrocolloid seal but it failed
- Experienced sore skin



Introduced Ostoform Seal with FLOWASSIST

- Used with 1-piece flat drainable pouching system



Feedback

- Patient's skin condition has improved
- Patient has continued to use the same pouching system and is no longer experiencing leakage
- Patient reported no leaks since Ostoform was introduced

Conclusion

Introducing Ostoform has improved this patient's quality of life. She is able to resume daily activities without the worry of leakage.